

SERVICE BULLETIN NO. MSB1078-144/7

I. TECHNICAL DETAILS

1.1 Category:

Mandatory

1.2 Airplanes affected:

Bezeichnung / Description	LBA Kennblatt-Nr. TCDS	EASA TCDS	FAA TCDS	Serial-Nr.
G 115C, C1, C2 G115D, D2	1078	EASA.A.364		82001-82084

1.3 Time of Compliance:

Item 1.8.1: Immediately after receipt of this Service Bulletin

Item 1.8.2: After receipt of new issue / revised pages

1.4 Subject:

ATA - Code: N/A

Revision of the aircraft documentation. Information about revision status.

1.5 Reason:

This Service Bulletin informs about the latest revision status of the Flight Manual / Maintenance Manual / Illustrated Parts Catalogue of the GROB G115C, G115D models. Future documentation changes will be published under MSB 1078-144, followed by /sequence number.

1.6 Concurrent documents:

N/A

1.7 Approval Note:

The technical content of this document is approved under the authority of EASA Design Organization Approval No. EASA.21J.030.

1.8 Accomplishment/ Instructions

- 1.8.1 Check aircraft documentation for correct issue and revision status in accordance with the list below.
1.8.2 Incorporate latest revisions into the respective Manual G 115E

G 115C, G 115D	Deutsche Ausgabe	English Issue
Flughandbuch Flight Manual C	Revision 6, 15. September 1997	Revision 6, 15. September 1997
Flughandbuch Flight Manual C2	Revision 3, 15. September 1997	Revision 5, 15. September 1997
Flughandbuch Flight Manual D	Revision 4, 15. September 1997	Revision 6, 15. September 1997 Optional Revision 7 10. November 1999 (see note)
Flughandbuch Flight Manual D2	Revision 6, 15. September 1997	Revision 11, 15. September 1997
Wartungshandbuch Maintenance Manual	N/A	Issue 3, Revision 6, 09. August 2010
Ersatzteilkatalog Illustrated Parts Catalogue	Ausgabe 1, Revision 7, 04. März 2011	Issue 1, Revision 7, 04. March 2011

Note: Revision 7 (English Issue) to the Flight Manual G115D resulted from the optional installation of the "Cold Weather Kit". Depending on implementation, either the a.m. revision status or the previous revision status of the Flight Manual is possible. To eliminate this ambiguity, the next revision of the Flight Manual G115D will bring the Flight Manual to a common revision standard, regardless of aircraft modification standard.

1.9 Repetitive Actions

N/A

II. PLANNING INFORMATION

2.1 Weight and CG

N/A

2.2 Material and Availability

All necessary revision pages for the affected manuals may be requested from GROB AIRCRAFT AG Customer Service..

2.3 Special Tools

N/A

2.4 Labor costs

N/A

2.5 Reference documents

See table 1.8

2.6 Credit

N/A

III. REMARKS

3.1 The exchange of the documentation may be performed by a qualified person / an authorised aviation workshop and has to be logged in the documentation Record of Revision Page(s).

3.2 If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us

3.3 For questions and assistance please contact:

Michael Reinhold, Customer Service,

phone: +49 (08268) 998 105

fax: +49 (08268) 998 200

e-mail: m.reinhold@grob-aircraft.com

e-mail: productsupport@grob-aircraft.com

SB-Index: <http://www.grob-aircraft.eu/service-and-support/g-115.html>